

**IMPACT TECHNOLOGY**  
608 7th St. NE Long Prairie, MN 56347  
866.848.4900

**HP**

														ACCESSORIES	
MAKE	MODEL	Total Meter	Color Meter	DF	Dup	FAX	PRT	SCAN	FIN	LCT	EC	IC	Comments	SN	
HP	2840C											2 3	Error code 59.4; unable to test	CNHC73405J	
HP	9050dn				x		x					2 3	4CF1 error cannot test or get meter	JPFL71Q038	
HP	CM-8050	1769355		x	x		x		C5959A	x		2 2		SG76BD1001	
HP	CM8050	487472	432640	x	x		x	x	C5959A			2 2	Missing LCT	SG76PD100H	
HP	CM8050	858189	305581	x	x		x	x	C5959A	x		2 2		SG76QD101N	
HP	Color LJ-3550	60361	51620				x					2 2		CNBR200948	
HP	Color LJ-3700dn						x					2 3	Throws front door error	CNGBX00083	
HP	Color LJ-3800N	104910	40551				x					2 2		CNTBC10279	
HP	Color LJ-5550n	7190	6117				x					2 2		JPSC79604Y	
HP	Color LJ-5550n	5288	3873				x					2 2		JpSC818060	
HP	LJ-2430N	27349					x					2 2		CNGKJ42378	
HP	LJ-2430N	34612					x					2 2		CNGKK42855	
HP	LJ-2430N	15570					x					2 2		CNGKK43312	
HP	LJ-2430N	27180					x					2 2		CNGKL44177	
HP	LJ-4050TN	43840					x					2 2		USCC002430	
HP	LJ-4101mfp			x								2 3	Missing Toner cannot test	USRGY22632	
HP	LJ-4101mfp			x			x					2 3	Missing Toner cannot test	USRGY22633	
HP	LJ-4101mfp			x			x					2 3	Missing Toner cannot test	USRGY22763	
HP	LJ-4101mfp			x			x					2 3	Missing Toner cannot test	USRGY22848	
HP	LJ-4101mfp			x			x					2 3	Missing Toner cannot test	USRGY22851	
HP	LJ-8000DN	475483					x					2 2		USBB017670	
HP	LJ-8000DN	1043882					x					2 2		USBB017812	
HP	LJ-8150	87463		x			x					2 2		JPBLL24165	
HP	LJ-8150N						x					2 2		USBF009997	
HP	LJ-9000	1959460			x		x					2 2		JPBMN03652	
														ACCESSORIES	
MAKE	MODEL	Total Meter	Color Meter	DF	Dup	FAX	PRT	SCAN	FIN	LCT	EC	IC	Comments	SN	
HP	LJ-M4345mfp			x								2 5	will not boot cannot test or get to meter	CNDC78Y08Y	
HP	OF-9110			x		x	x					2 3	Needs toners to work	CN5BN92039	