

**IMPACT TECHNOLOGY**  
608 7th St. NE Long Prairie, MN 56347  
866.848.4900

**RICOH**

				ACCESSORIES											
MAKE	MODEL	Total Meter	Color Meter	DF	Dup	FAX	PRT	SCAN	FIN	LCT	EC	IC	Comments	SN	
Gestetner	1502	120402		x							2	2		H6636600349	
Gestetner	1802D	197931		x	x		x				2	2		H6826301666	
Gestetner	2212	212221		x	x		x	x			2	2		J0121401402	
Gestetner	2212	51265		x	x						2	2		J0122403959	
Gestetner	3532	797673		x	x		x				2	2		J5836301905	
Gestetner	3532	733265		x	x						2	2		J5836401161	
Gestetner	5450	1785803			x						2	3	Missing Drum/Cant test	AT19110005	
Gestetner	5502	2518366		x	x				SR870		2	2		J5330900069	
Gestetner	5502	1729239		x	x		x		SR870		2	2		J5331100739	
Gestetner	5502	2660629			x				SR870		2	2		J5331200835	
Gestetner	C7535hdn	22588	1062				x				2	2		Q3851100166	
Gestetner	DSC-530	524207	174259	x	x		x	x	Hanging Finisher		2	2		L376540081	
Gestetner	DSc224	242609	34853	x	x	x	x	x			2	2	SC863-09 Startup without HD Data Lead	J2546101790	
Gestetner	DSc328	17433	9765	x	x	x	x	x			2	2		K4340700200	
Gestetner	DSc332	919168	118106	x	x	x	x	x	SR920		2	2	Missing 4 toners	K0200800320	
Gestetner	DSC338	202372	106838	x	x	x	x	x	SR-920		2	2		K0341100956	
Gestetner	DSc428	73464	20481	x	x	x	x	x	SR960		2	2		K5250700347	
Gestetner	DSc428	174657	8762	x	x	x	x	x			2	2		K5250800349	
Gestetner	DSc428	28748	2476	x	x	x	x				2	2		K5260200513	
Gestetner	DSc428	358334	129232	x	x		x	x			2	3	SC819 Fatal Kernel Mismatch Error	K5260200607	
Gestetner	DSc435	870581	654180	x	x		x	x			2	2	Missing 4 toners	K5050903433	
Gestetner	DSc525	179090	58840	x	x	x	x	x			2	2		L3675101500	
Gestetner	DSC530	323133	15620	x	x	x	x	x			2	2		L3766000370	
Gestetner	DSc535	175882	38300	x	x		x	x	SR790		2	2		L8966920734	
Gestetner	DSc535	296125	108534	x	x	x	x	x	SR790		2	2		L8967020475	
				ACCESSORIES											
MAKE	MODEL	Total Meter	Color Meter	DF	Dup	FAX	PRT	SCAN	FIN	LCT	EC	IC	Comments	SN	
Gestetner	DSm 735e	221290		x	x		x	x	SR790		2	2		M2775601287	
Gestetner	DSM-168D	164121		x	x						2	2		J9256501868	
Gestetner	DSM-721D										2	3	unable to clear user code, Cannot get into user tools	L7076141158	
Gestetner	DSm-730	183675		x	x	x					2	2		K8665300200	
Gestetner	DSm618d	144903		x	x		x	x			2	3	will not copy no error code	J9256401001	
Gestetner	DSm635	485258		x	x						2	2		K2855302338	
Gestetner	DSm645	1238474		x	x				SR790		2	2		K2955500430	
Gestetner	DSm651	3397727		x	x				SR850		2	2		K4455000279	
Gestetner	DSm651	762976		x	x		x	x			2	2		K4455600018	
Gestetner	DSm725	113391		x	x						2	2		K8555700590	
Gestetner	DSm735	163637		x	x		x	x	SR880		2	2		K9365002440	
Gestetner	DSm745	238371		x	x	x	x	x			2	2		K2945301760	
Gestetner	DSm745	456239		x	x		x	x			2	2		K9465100005	
Gestetner	GDS-M635	1150554		x	x	x	x	x			2	2		K2845500491	
Lanier	5227	456430		x	x	x					2	2		L0570070128	
Lanier	5470	2148825		x	x				SR-740		2	2		L0721070098	
Lanier	5470	1812454		x	x		x		SR-740	x	2	3	Error Code SC-705/RADF Bottom Plate Motor Error	L0722010098	
Lanier	5518	93036		x	x						2	2		L0981910190	
Lanier	5622	169446		x	x						2	2		J0122301535	
Lanier	LC430	299352	71387	x	x		x	x			2	2		L3775500306	
Lanier	LD-075	3427718		x	x		x	x	SR-850		2	2		J4345300407	
Lanier	LD-151	2757099		x	x				SR-850		2	2		K4464900396	
Lanier	LD-151	1479477		x	x						2	2		K4465300321	
Lanier	LD-175	1999215		x	x				SR-850		2	2		K4665200224	
Lanier	LD-175	2663459		x	x		x	x	SR-850		2	2		K6945900091	
				ACCESSORIES											
MAKE	MODEL	Total Meter	Color Meter	DF	Dup	FAX	PRT	SCAN	FIN	LCT	EC	IC	Comments	SN	
Lanier	LD-260	1246214		x	x		x	x	SR-970		2	2		M9285200724	

**IMPACT TECHNOLOGY**  
608 7th St. NE Long Prairie, MN 56347  
866.848.4900

**RICOH**

Lanier	LD-260C	667607	317360	x	x			x	x	SR-4020		2	2		M7980300485
Lanier	LD-345	173416		x	x			x	x			2	2		M2874901103
Lanier	LD0105	5297345		x	x			x	x	FS841	x	2	2	Folder Unit & Hole Punch	J7150400020
Lanier	LD015spf	47172		x		x		x	x			2	2		K2159500378
Lanier	LD024C	1116298	602270	x	x			x	x			2	2		J2536301001
Lanier	LD035	608552		x	x					SR790	x	2	2		J586302243
Lanier	LD060	2329655		x	x			x				2	2		J4225800282
Lanier	LD090	3314191		x	x			x	x	MJ1026	x	2	2		EK510470
Lanier	LD090	10076192		x	x					SR8840	x	2	2		J7040600495
Lanier	LD090	7031768		x	x					SR840	x	2	2		J7040800292
Lanier	LD090	7285857		x	x					SR840	x	2	2		J7040800306
Lanier	LD090	10435979		x	x					SR840	x	2	2		J7040800348
Lanier	LD090	7433033		x	x					SR840	x	2	2		J7051100128
Lanier	LD122	349716		x	x			x	x	SR820		2	2		J8345401807
Lanier	LD122	98329		x	x	x	x			SR-790		2	3	Error Code SC-542/Fuser Temp warmup error	J8345402135
Lanier	LD122	277259		x	x			x	x			2	2		J8355500549
Lanier	LD127	301730		x	x			x	x			2	2		J8455300844
Lanier	LD135	1250569		x	x							2	2		J7946101459
Lanier	LD135	395171		x	x	x	x	x	x	SR790	x	2	2		K2855201551
Lanier	LD160	1423103		x	x			x	x	SR850		2	2		K6855200017
Lanier	LD160C	493722	74492	x	x			x	x	SR4000		2	2	Missing all 4 toners	K5960600268
Lanier	LD160C	481245	154252	x	x			x	x	SR970		2	2		K5971000198
Lanier	LD190	2050062		x	x			x	x	SR5000		2	2		L5570400323
Lanier	LD225	282474		x	x			x	x	SR790		2	2		K8565500246

**ACCESSORIES**

MAKE	MODEL	Total Meter	Color Meter	DF	Dup	FAX	PRT	SCAN	FIN	LCT	EC	IC	Comments	SN	
Lanier	LD228C	221534	42093	x	x	x	x	x	SR920			2	2		K4350200294
Lanier	LD230	392066		x	x				SR820			2	2		K8665000153
Lanier	LD235	720750		x	x	x	x	x	SR790			2	2		K9364901785
Lanier	LD235	706209		x	x	x	x	x	SR880			2	2		K9365000907
Lanier	LD238C	406590	177427	x	x			x	SR-920			2	2		K0350200939
Lanier	LD245	120353		x	x	x	x	x	SR880	x		2	2		K9465300681
Lanier	LD245SP	525653		x	x	x	x	x	SR-880			2	3	says a cover is open, cannot make it say cover closed, cannot pass copy	K9455801016
Lanier	LD255	1261315		x	x				SR-970			2	2		L7765800030
Lanier	LD255	1276487		x	x				SR-970			2	2		L7775300676
Lanier	LD265	4059424		x	x			x	SR970	x		2	2	Require HDD for scan to function	K6755300348
Lanier	LD265	2330151		x	x			x	SR970			2	2		L8175700257
Lanier	LD316	33733		x	x	x	x	x				3	2	ADF Discolored	L6876740777
Lanier	LD335	705677		x	x	x	x	x	SR790			3	2	Yellowed	M2775002239
Lanier	LD335	828610		x	x							2	2		M2775401113
Lanier	LD345	229696		x	x				SR790	x		2	2		M2775500210
Lanier	LD345	38385		x	x	x	x	x	SR790			2	2		M2866000275
Lanier	LD345	224432		x	x				SR790			2	2		M2875500967
Lanier	LD345c	177432		x	x	x	x	x	SR790			2	2		M2866000572
Lanier	LD345c	36517		x	x	x	x	x	SR790			2	2		M2874900865
Lanier	LD420C	43335	16427	x	x			x	x			2	2		M5084900080
Lanier	LD425C	87247	41161	x	x	x	x	x				2	2	Missing Toners	65300308
Lanier	LD425c	185717	127966	x	x			x	x			2	2	Missing 4 Toners	L365401509
Lanier	LD425C	222119	8499	x	x			x	SR790			2	2		L3685100804
Lanier	LD425C	210730	15814	x	x	x	x	x	Hanging			2	2		L3685600347
Lanier	LD430C	141968	101794	x	x			x	x			2	2		L3775100129

**ACCESSORIES**

MAKE	MODEL	Total Meter	Color Meter	DF	Dup	FAX	PRT	SCAN	FIN	LCT	EC	IC	Comments	SN	
Lanier	LD433	165988		x	x	x	x	x				2	2		M6385400144
Lanier	LD435C	324878	76301	x	x	x	x	x				2	2		L8976321588
Lanier	LD435c	214705	17850	x	x			x	x			2	2		L8986520264
Lanier	LD445C	302347	151803	x	x			x	SR-790			2	2		L9067020245
Lanier	LD445C	324466	52062	x	x			x	SR790			2	2		L9076420763
Lanier	LD445C	479621	26230	x	x			x	SR790			2	2		L9077020783
Lanier	LD445C	422400	53	x	x			x	SR3000			2	2		L9077220396

**IMPACT TECHNOLOGY**  
608 7th St. NE Long Prairie, MN 56347  
866.848.4900

**RICOH**

Lanier	LD445C	278676	40238	x	x	x	x	x				2	2		L9086720457
Lanier	LD520C	152657	15931	x	x	x	x	x				2	2		V2286000993
Lanier	LF416e	98902				x						2	2		A4669100281
Lanier	LF416e	235560				x						2	2		A466910278
Lanier	LP226cn	5101	1160					x				2	2		Q7079100163
Lanier	LP440C	617873	26557		x			x				2	2		Q8077040133
Lanier	SPC400DN	20867	19128					x				2	2		Q6888500088
Ricoh	1170L					x						2	2		A4868800587
Ricoh	2051SP											2	3	Will not boot up/ Cannot test	K6754900065
Ricoh	2060SP	3082630		x	x			x	x	SR850	x	2	2		K6845900007
Ricoh	2210L					x						2	2		A4969200033
Ricoh	3245C	1337479	208854	x	x			x	x			2	2		K5150300339
Ricoh	3310	92076		x	x	x						2	2		A3568500241
Ricoh	3310e	10746				x						2	2		A3559102089
Ricoh	3310L	90263				x						2	2		A3549301820
Ricoh	3310Le	45866				x						3	2	ADF Tray cracked	A3559002323
Ricoh	3310LE	2193				x						2	2		A3559200585
Ricoh	3310LE	1		x	x	x						2	2	Counter was cleared	A3568500848

**ACCESSORIES**

MAKE	MODEL	Total Meter	Color Meter	DF	Dup	FAX	PRT	SCAN	FIN	LCT	EC	IC	Comments	SN	
Ricoh	4410L	10871		x		x						2	2		A4549400827
Ricoh	4420L	88922		x	x	x						2	2		A4578500190
Ricoh	4420NF	135447		x	x	x						2	2		A4669000163
Ricoh	4420NF	19625				x						2	2		A4669000202
Ricoh	4420nf	1531		x	x	x	x					2	2		A4669100058
Ricoh	4420nf	1783		x	x	x	x					2	2		A4669200001
Ricoh	442NF	163266			x							2	2		A4659300107
Ricoh	5510NF	11073				x						2	2		A3820700111
Ricoh	5510NF	1963				x						2	2		A3850690018
Ricoh	AF 1515MF	50892		x	x	x		x				2	2		K2168700034
Ricoh	AF 2022SP	311424		x	x			x	x			3	2	Broken wheel	J8355102612
Ricoh	AF-1013	146943			x			x				2	2		H9029400197
Ricoh	AF-1013	75767										2	2		H9038700622
Ricoh	AF-1013	10585		x								2	2		H9039202725
Ricoh	AF-1013f	271215		x		x	x	x				2	2		H9219601415
Ricoh	AF-1013f	137316				x						2	2		H9228902074
Ricoh	AF-1013F	105615		x	x	x						2	2		H9229000770
Ricoh	AF-1013f	156297		x		x						2	2		H9229100073
Ricoh	AF-1013F	49087		x		x						2	2		H9238501480
Ricoh	AF-1013F	91384			x	x	x					2	2		H9239002707
Ricoh	AF-1013f	84669		x	x	x						2	2		H9239403065
Ricoh	AF-1013f	56971		x		x	x	x				2	2		H9248503282
Ricoh	AF-1015	193467		x		x						2	2		H6626104196
Ricoh	AF-1015	55158		x		x						2	2		H6626104487
Ricoh	AF-1015	204326		x								2	2		H6626105128

**ACCESSORIES**

MAKE	MODEL	Total Meter	Color Meter	DF	Dup	FAX	PRT	SCAN	FIN	LCT	EC	IC	Comments	SN	
Ricoh	AF-1015	245052		x								2	2		H6626503143
Ricoh	AF-1015	101807		x		x						3	2	3 Broken Wheels	H6626704674
Ricoh	AF-1015	122846		x	x	x						2	2		H6626704750
Ricoh	AF-1015	38861		x								2	2		H6636405091
Ricoh	AF-1015	443727		x		x	x					2	2		H6636902515
Ricoh	AF-1015	220845		x	x							2	2		H6637101131
Ricoh	AF-1018	44390		x								2	2		H6736600055
Ricoh	AF-1018D	508464		x	x							2	2		H6817201348
Ricoh	AF-1018D	237169		x	x			x							H6826701580
Ricoh	AF-1018D	414584		x		x						2	2		H6826802361
Ricoh	AF-1018D	346405		x	x							2	2		H6836101902
Ricoh	AF-1022	338359		x	x	x	x	x				2	2		122400824
Ricoh	AF-1022	396688		x	x							2	2		J0111102819
Ricoh	AF-1022	721129		x	x							2	2		J0121402762
Ricoh	AF-1022	191443		x	x	x	x					2	2		J0121701070
Ricoh	AF-1022	377053		x	x							2	2		J0121802092
Ricoh	AF-1027	645845		x	x	x	x	x				2	2		J0211000037

**IMPACT TECHNOLOGY**  
608 7th St. NE Long Prairie, MN 56347  
866.848.4900

**RICOH**

Ricoh	AF-1027	125636		x	x		x	x	SR790		2	2		J0230500900
Ricoh	AF-1035	422582		x	x	x	x	x	SR720		2	2		H7015901199
Ricoh	AF-1035	326953		x	x	x	x	x	SR-720		2	2		H7030100023
Ricoh	AF-1035P	491776		x	x	x	x	x			2	2		H7226200083
Ricoh	AF-1050	2777675			x				SR810	x	2	2	passes paper no image	H3701000117
Ricoh	AF-1055	570740		x	x				SR870		2	2		J5340600747
Ricoh	AF-1060	944883		x	x				SR8750		2	2		J4235100892
Ricoh	AF-1060	232290		x	x		x	x	SR-850		2	2	DOD'D	J4235200368

**ACCESSORIES**

MAKE	MODEL	Total Meter	Color Meter	DF	Dup	FAX	PRT	SCAN	FIN	LCT	EC	IC	Comments	SN
Ricoh	AF-1060	1440536		x	x				SR-850		2	2		J4235300319
Ricoh	AF-1060	1938668		x	x		x	x	SR850		2	2		J4235300471
Ricoh	AF-1060	739312		x	x		x	x	SR-850	x	3	2	Left side of touch screen is fuzzy.	J4235600643
Ricoh	AF-1060	1807452		x	x		x	x			2	2		J4244900639
Ricoh	AF-1060	1761339			x		x	x			2	2		J4245000222
Ricoh	AF-1060	2422429		x	x		x	x			2	5	SC819 Firmware issue	J4245000310
Ricoh	AF-1060	1738735		x	x		x	x			2	2		J4245000321
Ricoh	AF-1060	1409172		x	x		x	x			2	2		J4245000786
Ricoh	AF-1060	2044592		x	x		x	x	SR850		2	2		J4245001144
Ricoh	AF-1060	549126		x	x		x	x	SR-850	x	2	2		J4245101009
Ricoh	AF-1060	369537		x	x		x	x	SR850		2	2		J4245300369
Ricoh	AF-1060	1613866		x	x		x	x			2	2		J4245300670
Ricoh	AF-1075	1497109		x	x		x	x	SR-850		2	2		J4335300408
Ricoh	AF-1180L						x				2	2		A5579500039
Ricoh	AF-1232C	128187	7473	x	x	x	x	x	SR790		2	2		J2630900222
Ricoh	AF-1515	49215		x	x						2	2		K2049102692
Ricoh	AF-1515	24683		x							2	2		K2059200683
Ricoh	AF-1515	60897		x	x						2	2		K2068800329
Ricoh	AF-1515	91691		x							2	2		K2069200181
Ricoh	AF-1515	120847		x		x	x	x			2	2		K2159000675
Ricoh	AF-1515	63348		x		x	x	x			2	2		K2159201069
Ricoh	AF-1515F	75988		x	x	x					2	2		K2258800342
Ricoh	AF-1515F	33375		x		x					2	2		K2269100340
Ricoh	AF-1515MF	55747		x		x	x	x			2	3	SC302 error	K2158801461
Ricoh	AF-1515MF	295032		x		x	x	x	NA		2	3	Keeps jamming/ Cannot pass a copy	K2169202591

**ACCESSORIES**

MAKE	MODEL	Total Meter	Color Meter	DF	Dup	FAX	PRT	SCAN	FIN	LCT	EC	IC	Comments	SN
Ricoh	AF-2016	78562		x		x	x	x			2	2		K8166341567
Ricoh	AF-2020	5558		x							2			K8266940068
Ricoh	AF-2020D	68391		x	x						2	2		K8356801270
Ricoh	AF-2020D	367235		x	x	x	x	x			3	2	Crack on front cover	K8356941188
Ricoh	AF-2020D	40702		x	x						2	2		K8366240213
Ricoh	AF-2020D	82361		x	x						2	2		K8366641768
Ricoh	AF-2022	343680		x	x				SR-790		2	2		8332402465
Ricoh	AF-2022	39823		x	x						2	2		J8345601171
Ricoh	AF-2022sp	135618		x	x	x	x	x			2	2		J8355002029
Ricoh	AF-2027sp	836007		x	x		x	x			3	4	missing drum unit/bypass door broke/cannot test	J8445400137
Ricoh	AF-2027sp	74742		x	x	x	x	x			2	2		J8455101127
Ricoh	AF-2035	558008		x	x						2	2		J5836500170
Ricoh	AF-2035	541793		x	x	x	x	x	SR-790		2	2		J5837000526
Ricoh	AF-2035e	1045458		x	x	x	x	x			2	2		J7946100409
Ricoh	AF-2035E	595004		x	x	x	x	x			2	2		K2845301960
Ricoh	AF-2035e	401138		x	x				SR790		2	2		K2845402187
Ricoh	AF-2035e	1113672		x	x				SR790		2	2		K2845402188
Ricoh	AF-2035e	783152		x	x				SR790		2	2		K2845402213
Ricoh	AF-2035e	765524		x	x	x	x	x	SR790		2	2		K2854900794
Ricoh	AF-2035e	87391		x	x	x	x	x	SR-790		2	2	missing part of bridge unit	K2854901434
Ricoh	AF-2035e	739523		x	x	x			SR880		2	2		K2855100002
Ricoh	AF-2035esp	1181785		x	x	x	x				2	2		K2845302052
Ricoh	AF-2035esp	960211		x	x	x	x	x	SR790		2	2		K2845701978

**IMPACT TECHNOLOGY**  
608 7th St. NE Long Prairie, MN 56347  
866.848.4900

**RICOH**

Ricoh	AF-2035esp	371626		x	x	x				SR-790		2	3	SC-420/Cleaning Motor Lock	K284902016
Ricoh	AF-2035esp	363213		x	x	x	x	x				2	2		K2855101007
<b>ACCESSORIES</b>															
MAKE	MODEL	Total Meter	Color Meter	DF	Dup	FAX	PRT	SCAN	FIN	LCT	EC	IC	Comments		SN
Ricoh	AF-2035esp	1318904		x	x	x	x	x	SR790		2	2			K2855402321
Ricoh	AF-2035esp	1549297		x	x	x	x	x			2	2			K2855500341
Ricoh	AF-2035sp	446284		x	x	x	x	x			2	2			J5836401746
Ricoh	AF-2035sp	628215		x	x	x	x	x			2	2			J5836403872
Ricoh	AF-2045	926112		x	x	x					2	2			J5836901899
Ricoh	AF-2045e	569999		x	x	x	x	x		x	2	2			K2945801231
Ricoh	AF-2045e	1592064		x	x	x					2	2			K2945801851
Ricoh	AF-2045E	925362		x	x				SR880	x	2	2			K2946000361
Ricoh	AF-2045esp	1064875		x	x	x	x	x	SR880		2	2			K2945702056
Ricoh	AF-2045sp	666663		x	x	x	x	x	SR880	x	2	2			J5936700028
Ricoh	AF-2045sp	983150		x	x		x	x			2	4		SC541 fuser error right side door does not close all the way can not test	J5936901639
Ricoh	AF-2045sp	1413899		x	x	x	x	x			2	2			J5937203395
Ricoh	AF-2051	2064635		x	x		x	x	SR850		2	2			K4455800070
Ricoh	AF-2051	2060624		x	x		x	x	SR850		2	2			K6745900234
Ricoh	AF-2051	1750653		x	x		x	x	SR850		2	2			K6755100471
Ricoh	AF-2051sp	492812		x	x		x	x	SR850		2	2			K6755300400
Ricoh	AF-2051sp	838238		x	x		x	x	SR850		2	2			K6755400062
Ricoh	AF-2051SP	991766		x	x		x	x	SR-850		2	2			K6755700380
Ricoh	AF-2051sp	237395		x	x		x	x	SR841		2	2			K6755900300
Ricoh	AF-2051sp	604041		x	x		x	x	SR850	x	2	2			K6755900394
Ricoh	AF-2051SP	1177491		x	x		x	x	SR850		2	2			K6764900105
Ricoh	AF-2051SP	669484		x	x		x	x			2	3		SC672 Controller to Operation Panel Communication Error at Startup	KG764900475
Ricoh	AF-2060	208075		x	x				SR-850		2	2			K4564100178
Ricoh	AF-2060	505322		x	x				SR-850		2	2		DOD'D	K456500075
Ricoh	AF-2060	265302		x	x				SR-850		2	2			K4565300434
<b>ACCESSORIES</b>															
MAKE	MODEL	Total Meter	Color Meter	DF	Dup	FAX	PRT	SCAN	FIN	LCT	EC	IC	Comments		SN
Ricoh	AF-2060	383514		x	x				SR-850		2	2			K4565400048
Ricoh	AF-2060	213044		x	x				SR-850		2	2			K4565400059
Ricoh	AF-2060	483464		x	x				SR-850		2	2			K4565900266
Ricoh	AF-2060SP	2330786		x	x		x	x	SR-850	x	2	2			K6845900143
Ricoh	AF-2075	1526887		x	x		x	x	SR-850		2	2			K6955700071
Ricoh	AF-2075	2138132		x	x		x	x	SR-850		2	3		Cannot test, says internal tray is full cannot clear it.	K6955700254
Ricoh	AF-2105	3448107		x	x		x		SR-841	x	2	2		NO HD	J7151100019
Ricoh	AF-2105	6366242		x	x		x		SR-841	x	2	2		Top Paper Drawer Broken, NJo HD	J7151100026
Ricoh	AF-2105	5681517		x	x		x		SR-841	x	2	2		NO HD	J7151100027
Ricoh	AF-2105	7222149		x	x		x		SR-841	x	2	2		SC503 Drawer 3 (or 2nd) Lift Motor Malfunction 3rd Paper Tray Error, No HD	J7151100050
Ricoh	AF-2105	6212270			x				SR-841	x	2	2			J7151100054
Ricoh	AF-2105	6325644		x	x				SR841		2	2		HDD Error	J7151100078
Ricoh	AF-2105	4890121		x	x		x		SR-841	x	2	2		NO Hard Drive	J7151100119
Ricoh	AF-2228C	1342130	148297	x	x	x	x	x	SR920		2	2			K0341200600
Ricoh	AF-2228C	916429	79325	x	x	x	x	x	SR920		2	2		missing fax button	K4340800244
Ricoh	AF-2228C	440984	50333	x	x	x	x	x	SR920		2	2			K4341100392
Ricoh	AF-2232C	330198	40471	x	x	x	x	x			2	2			K0231200512
Ricoh	AF-2232C	431808	69215	x			x	x	SR-960		2	2			K0240100716
Ricoh	AF-2232C	1072336	149744	x	x	x	x	x			2	2		No toners	K0240300175
Ricoh	AF-2232C	367609	66272	x	x		x	x			2	2			K0240300215
Ricoh	AF-2232C	436017	36013	x	x		x	x	SR920		2	2			K0240700072
Ricoh	AF-2232C	456418	139019	x	x		x	x	SR910		2	2			K0241200574
Ricoh	AF-2238C	297371	105581	x	x	x	x	x	SR920		2	2			K0331200330

**IMPACT TECHNOLOGY**  
608 7th St. NE Long Prairie, MN 56347  
866.848.4900

**RICOH**

Ricoh	AF-2238C	1081388	365323	x	x	x	x	x	SR920		3	2	Yellowed	K0331200799
Ricoh	AF-2238C	528702	36314	x	x	x	x	x			2	2		K0340501068
<b>ACCESSORIES</b>														
MAKE	MODEL	Total Meter	Color Meter	DF	Dup	FAX	PRT	SCAN	FIN	LCT	EC	IC	Comments	SN
Ricoh	AF-2238C	159945	32360	x	x	x	x	x	SR920		2	2		K0340701301
Ricoh	AF-2238C	874389	271825	x	x	x	x	x	SR920		2	2	No Toner	K0340900316
Ricoh	AF-2238C	599560	38795	x	x		x	x	SR920		2	2		K0341000433
Ricoh	AF-2238C	373547	16857	x	x	x	x	x			2	2		K0341200789
Ricoh	AF-2238C	216212	82846	x	x	x	x	x	SR910		2	2		K0341201103
Ricoh	AF-2238C	1874603	642586	x	x	x	x	x	SR920		2	2		K0350100736
Ricoh	AF-2238C	112115	79744	x	x	x	x	x			4	2	Back, side, & duplex cover broken	K0350400982
Ricoh	AF-240W	69917									2	2	Has interface for external controller/ controller missing	L3060400005
Ricoh	AF-3025	142952		x	x		x				2	2		K8555701962
Ricoh	AF-3025	288891		x	x		x	x			2	2		K8556002433
Ricoh	AF-3025	180301		x	x	x	x	x			2	2		K8565101735
Ricoh	AF-3025	444365		x	x	x	x	x	SR820		2	2		K8565201526
Ricoh	AF-3025	185808		x	x		x	x			2	2		K8565501750
Ricoh	AF-3025	459588		x	x	x	x	x			2	2		K8565602216
Ricoh	AF-3025	653092		x	x		x	x			2	2		K8565602316
Ricoh	AF-3025	422899		x	x	x	x	x			2	2		K8565602319
Ricoh	AF-3025	62600		x	x	x	x	x			2	2		K8565602736
Ricoh	AF-3025	305432		x	x	x	x	x			2	2		K8565700170
Ricoh	AF-3025	209444		x	x		x	x			2	2		K8565701002
Ricoh	AF-3030	147344		x	x	x	x	x	SR790		2	2		K8656000220
Ricoh	AF-3030	287825		x	x	x	x	x	SR820		2	2		K8656001336
Ricoh	AF-3030	211767		x	x		x	x			2	2		K8664900296
Ricoh	AF-3030	207616		x	x				SR-790		2	3	Paper Jams in Fuser	K8665100465
Ricoh	AF-3030	189904		x	x				SR790		2	2		K8665101031
Ricoh	AF-3030	176812		x	x				SR790		2	2		K8665101075
<b>ACCESSORIES</b>														
MAKE	MODEL	Total Meter	Color Meter	DF	Dup	FAX	PRT	SCAN	FIN	LCT	EC	IC	Comments	SN
Ricoh	AF-3030	327133		x	x				SR790		2	2		K8665101106
Ricoh	AF-3030	172484		x	x				SR790		2	2		K8665101110
Ricoh	AF-3030	220168		x	x	x	x	x	SR790		2	2		K8665200805
Ricoh	AF-3035	1391969		x	x	x	x	x	SR790		2	2		K9356000644
Ricoh	AF-3035	199116		x	x		x	x			2	2		K9364901031
Ricoh	AF-3035	68996		x	x	x	x	x	SR790		2	2		K9365000295
Ricoh	AF-3035	347634		x	x	x	x	x	SR-790		2	2		K9365401104
Ricoh	AF-3035	225541		x	x	x	x	x	SR880		2	2		K9365401144
Ricoh	AF-3035	348350		x	x						2	2		K9365700791
Ricoh	AF-3035	209672		x	x		x	x			2	2		K9365901308
Ricoh	AF-3035sp	647492		x	x	x	x	x	SR790		2	2		K9355802626
Ricoh	AF-3045	917358		x	x	x	x	x	SR880		2	2		K9455700599
Ricoh	AF-3045	169652		x	x	x					2	2	Missing LCT & Fin	K9455701237
Ricoh	AF-3045	1303512		x	x		x	x	SR790		2	2		K9464901841
Ricoh	AF-3045	948818		x	x	x	x	x	SR790		2	2		K9465200388
Ricoh	AF-3045	850636		x	x	x	x	x	SR880	x	2	2	no hdd for universal send	K9465200408
Ricoh	AF-3045	478334		x	x	x	x	x	SR790	x	2	3	LCD screen does not work	K9465300940
Ricoh	AF-3045	784653		x	x				SR-790		2	2		K9465301241
Ricoh	AF-3045	576493		x	x	x		x	SR-790		2	2		K9465301499
Ricoh	AF-3045	698852		x	x		x	x			2	2		K9465402530
Ricoh	AF-3045	135509		x	x	x	x	x	SR790		2	2		K9465601822
Ricoh	AF-3045	1316769		x	x		x	x	SR880	x	2	2		K9465700144
Ricoh	AF-3045	472501		x	x	x	x	x	SR-970		2	2		K9465701744
Ricoh	AF-3045	219730		x	x	x	x	x	SR790		2	2		K9465901619
Ricoh	AF-3224C	103314	33635		x	x	x	x			2	2		K7156300209
<b>ACCESSORIES</b>														
MAKE	MODEL	Total Meter	Color Meter	DF	Dup	FAX	PRT	SCAN	FIN	LCT	EC	IC	Comments	SN
Ricoh	AF-3224C	203015	16930	x	x	x	x	x			2	2		K7156300309

**IMPACT TECHNOLOGY**  
608 7th St. NE Long Prairie, MN 56347  
866.848.4900

**RICOH**

Ricoh	AF-3224C	105107	61234	x	x	x	x	x			2	2		K7156400551
Ricoh	AF-3224C	48031	27670	x	x	x	x	x			2	2		K7156700151
Ricoh	AF-3224C	293172	18961	x	x	x	x	x		Hanging	2	2		K7156810147
Ricoh	AF-3224C	234280	36545	x	x	x	x	x			2	2		K7156910109
Ricoh	AF-3224C	73789	2938	x	x	x	x	x			2	2		K7156910169
Ricoh	AF-3224C	101660	3350	x	x	x	x	x		SR830	2	2		K7166110417
Ricoh	AF-3228C	137490	101974	x	x		x	x			2	2		K5250300997
Ricoh	AF-3228C	138363	39531	x	x	x	x	x			2	2		K5250800728
Ricoh	AF-3228C	351989	225971	x	x		x	x			4	3	Missing right side door cannot test	K5251000248
Ricoh	AF-3228C	955403	430167	x	x	x	x	x		SR960	2	2		K5251200082
Ricoh	AF-3235C	453790	136578	x	x	x	x	x			2	2	No toners	K5050300220
Ricoh	AF-3235C			x	x		x	x		SR920	4	3	Machine does not boot/Duplex cover broken	K5050700389
Ricoh	AF-3235C	846326	251737	x	x		x	x			2	2		K5050700847
Ricoh	AF-3235C	508624	137111	x	x	x	x	x		SR-960	2	2		K5050900450
Ricoh	AF-3235C	538611	216138	x	x	x	x	x		SR960	2	2		K5050902969
Ricoh	AF-3235C			x	x					SR-950	2	4	Machine Powers up/Machine doesnt not boot/Cant test or get to options or meter	K5051000160
Ricoh	AF-3235C	70272	29922	x	x		x	x		SR960	2	2	no hdd for universal send	K5051000786
Ricoh	AF-3235C	429390	61267	x	x	x	x	x		SR-960	2	2		K5051000813
Ricoh	AF-3235C	513054	202804	x	x		x	x		SR960	2	2		K5051000822
Ricoh	AF-3235C	394114	190792	x	x		x	x			2	2		K5058700766
Ricoh	AF-3235C	290161	71039	x	x	x	x	x		SR960	2	2		K5060300075
Ricoh	AF-3235C	397530	73644	x	x	x	x	x			2	2		K5060400007
Ricoh	AF-3235C	378554	57221	x	x		x	x		SR-960	2	2		K5060500117
Ricoh	AF-3235C				x	x	x				3	2	Wont boot up past the Please Wait... screen	K5060600650

**ACCESSORIES**

MAKE	MODEL	Total Meter	Color Meter	DF	Dup	FAX	PRT	SCAN	FIN	LCT	EC	IC	Comments	SN
Ricoh	AF-3245C	715407	197980	x	x	x	x	x	SR-950		3	2	Discolored/Missing Four Toners	K5150300101
Ricoh	AF-3245C	411812	177030	x	x	x	x	x	SR960		2	2		K5150300138
Ricoh	AF-3245C	481268	235778	x	x	x	x	x	SR960		2	2		K5160200641
Ricoh	AF-3245C	744164	105122	x	x		x	x			2	2		K5160400548
Ricoh	AF-3245C	883199	151172	x	x	x	x	x	SR960		2	3	SC542 Fuser Temperature Warm-up Error	K5160400795
Ricoh	AF-3245C	475187	120732	x	x	x	x	x	SR960		2	2		K5160600233
Ricoh	AF-3260	660644	137057	x	x		x		SR-850		2	2		K5950700091
Ricoh	AF-3260C			x	x		x	x	SR980	x	2	3	Machine freezes on bootup	K5950800124
Ricoh	AF-3260C	943130	163339	x	x		x	x			2	2		K5950800159
Ricoh	AF-3260C	774741	359446	x	x		x	x	SR970		2	2		K5960400580
Ricoh	AF-3260C	310989	89131	x	x		x	x	SR970		2	2		K5970300020
Ricoh	AF-3260C	226818	117440	x	x		x	x	SR970		2	2		K5970300042
Ricoh	AF-3260C	979915	867736	x	x		x	x			2	2		L5950800129
Ricoh	AF-3320L	4363		x		x					2	2		A3579300718
Ricoh	AF-400	595744		x	x						x	2	2	9133
Ricoh	AF-410N	10279					x				3	2	Top dented	Q3166400126
Ricoh	AF-44101	134076		x		x					2	2		A4548500666
Ricoh	AF-4410L	55954				x					2	2		A4549300588
Ricoh	AF-4420NF	44250		x		x					2	2		A4659300189
Ricoh	AF-4430	36879				x					2	2		A4698500114
Ricoh	AF-4430L	30514				x					2	2		A4588900259
Ricoh	AF-4430L	31622		x	x	x		x			2	2		A4679600139
Ricoh	AF-470W	2539					x				2	2	missing controller	J2031100069
Ricoh	AF-550	813102		x	x				SR-740	x	2	4	Developer Unit Taken Apart/Cant test	A9049100167
Ricoh	AF-551	712525		x	x		x		SR740		2	3	SC990 code Software performance error	H4715201357

**ACCESSORIES**

MAKE	MODEL	Total Meter	Color Meter	DF	Dup	FAX	PRT	SCAN	FIN	LCT	EC	IC	Comments	SN
------	-------	-------------	-------------	----	-----	-----	-----	------	-----	-----	----	----	----------	----

**IMPACT TECHNOLOGY**  
608 7th St. NE Long Prairie, MN 56347  
866.848.4900

**RICOH**

Ricoh	AF-AC204			x		x					2	2		K2649400900
Ricoh	AF-AP3800C	593934	133573	x			x	x	SR770		2	2		P6011201194
Ricoh	AF-AP3800C	307557	267631				x				2	2		P6020100658
Ricoh	AF-AP3850C	441471	125124				x				2	2		P890700124
Ricoh	AF-AP410N	278379			x		x				2	2		Q3256900640
Ricoh	AF-AP4510	445635									2	2		P7266600052
Ricoh	AF-AP610N						x				2	2		Q3357200204
Ricoh	AF-AP610N						x				2	2		Q3357200206
Ricoh	AF-AP610N	51590					x				2	2		Q3367100702
Ricoh	AF-AP610N						x				2	2		Q3367100912
Ricoh	AF-AP610N	12439					x				2	2		Q3367100919
Ricoh	AF-AP610N						x				2	2		Q3367100920
Ricoh	AF-AP610N						x				2	2		Q3367100923
Ricoh	AF-AP610N						x				2	2		Q3367100924
Ricoh	AF-AP610N						x				2	2		Q3367100925
Ricoh	AF-AP610N						x				2	2		Q3367100926
Ricoh	AF-AP610N						x				2	2		Q3367101095
Ricoh	AF-AP610N						x				2	2		Q3367101100
Ricoh	AF-AP610N						x				2	3		Q3386100236
Ricoh	AF-AP8100	131841					x				2	2		Q8467200211
Ricoh	AF-C5560	111208	66475	x	x		x	x	SR-970		2	2		K6060400318
Ricoh	AF-C5560V	633367	429611	x	x		x	x	SR970		2	2		K6080200097
Ricoh	AF-CL3000	150418	60584				x				2	2		P9231200843
Ricoh	AF-CL3500N	77477					x				2	2		Q4460601059
Ricoh	AF-CL4000DN	61335	43978				x				2	2		Q2459101211

**ACCESSORIES**

MAKE	MODEL	Total Meter	Color Meter	DF	Dup	FAX	PRT	SCAN	FIN	LCT	EC	IC	Comments	SN
Ricoh	AF-CL4000DN	304187	103930				x				2	2		Q2459101226
Ricoh	AF-CL5000	166837	131444				x				2	2		P7536300446
Ricoh	AF-CL5000	13426	8503				x				2	2		P7536700914
Ricoh	AF-CL7000	468198	131778	x	x	x	x	x			2	2		P9630500104
Ricoh	AF-CL7100D	485320	451472				x				2	2		Q1340300154
Ricoh	AF-CL7200	31364	25107				x				2	2		Q3750700167
Ricoh	AF-CL7200	117703	40092				x				2	2		Q3751100049
Ricoh	AF-CL7200	120366	103309				x				2	2		Q3760300002
Ricoh	AF-CL7200	46494	29637				x				2	2		Q3770300018
Ricoh	AF-CL7200	20277	3413				x				2	2		Q3770500024
Ricoh	AF-CL7300	149126	124916				x				3	2	Front door damaged	Q3860600015
Ricoh	AF-MP 2550B	157083		x	x	x					2	2		M6485500338
Ricoh	AF-MP 4000B	264803		x	x	x					2	2		M5485400379
Ricoh	AF-MP C2500	237455	138844	x	x	x	x	x			2	2		L3675400356
Ricoh	AF-MP-161F	60621		x	x	x					2	2		L9989000014
Ricoh	AF-MP1100	11760088		x	x				SR5000	x	2	2		L5660900106
Ricoh	AF-MP1100	3247049		x	x		x	x	SR5000	x	2	2		L5661200133
Ricoh	AF-MP1100	2526857		x	x		x	x	SR5000	x	2	2		L5670500053
Ricoh	AF-MP1600	109739		x			x	x			2	2		L6806140023
Ricoh	AF-MP1600	168469		x	x	x	x	x			2	2		L6867100387
Ricoh	AF-MP1600	294324		x	x						2	2		L6867240109
Ricoh	AF-MP1600	85849		x		x					2	2		L6867240517
Ricoh	AF-MP1600	5537		x							2	2		L6876140802
Ricoh	AF-MP161	23403		x		x	x	x			5	5	Machine destroyed toner everywhere does not boot	L9989000286
Ricoh	AF-MP161	48155		x	x	x					2	2		L9989100200

**ACCESSORIES**

MAKE	MODEL	Total Meter	Color Meter	DF	Dup	FAX	PRT	SCAN	FIN	LCT	EC	IC	Comments	SN
Ricoh	AF-MP161	109511		x							2	2		M0178600778
Ricoh	AF-MP161	107269		x	x	x	x	x			2	2		M0179101012
Ricoh	AF-MP161	111567		x	x	x	x	x			2	2		M0179605732
Ricoh	AF-MP161	38908		x		x	x	x			2	2		M0179606175
Ricoh	AF-MP161	34204		x		x	x	x			2	2		M0188705957
Ricoh	AF-MP161	29415		x	x	x	x	x			2	2		M0188705960
Ricoh	AF-MP161	114784		x		x	x	x			2	2		M0188903186
Ricoh	AF-MP161	40448			x	x	x	x			2	2		M0189303035
Ricoh	AF-MP161	28504		x	x						2	2		M0289400124
Ricoh	AF-MP161	38057		x	x						2	2		M278900554

**IMPACT TECHNOLOGY**  
608 7th St. NE Long Prairie, MN 56347  
866.848.4900

**RICOH**

Ricoh	AF-MP2000	172931		x	x	x	x	x				2	2		7086141182
Ricoh	AF-MP2000	245639		x	x	x						2	2		L7076641620
Ricoh	AF-MP2000	11542		x	x	x	x	x				2	2		L7077040018
Ricoh	AF-MP2000	49556		x	x	x						2	2		L7086540343
Ricoh	AF-MP2000	23926		x	x	x						2	2		L7087240098
Ricoh	AF-MP2000	86519		x	x	x	x	x				2	2		L7087240108
Ricoh	AF-MP2000	40170		x	x	x						2	2		L7087240118
Ricoh	AF-MP2500	315061		x	x	x	x	x	Hangin Finisher			2	2		M4481800419
Ricoh	AF-MP2500C	186525	14907	x	x	x	x	x	SR-790			2	2		L3665300051
Ricoh	AF-MP2510	133775		x	x	x	x	x				2	2		M0965801512
Ricoh	AF-MP2510	360995		x	x		x	x				2	2		M0965902490
Ricoh	AF-MP2510	291834		x	x	x	x	x	SR790			2	2		M0974900564
Ricoh	AF-MP2510	252779		x	x		x	x				2	2		M0975601767
Ricoh	AF-MP2510	277778		x	x	x	x	x				2	2		M0975601770
Ricoh	AF-MP2510	327922		x	x	x	x	x				2	2		M0975601772

**ACCESSORIES**

MAKE	MODEL	Total Meter	Color Meter	DF	Dup	FAX	PRT	SCAN	FIN	LCT	EC	IC	Comments	SN	
Ricoh	AF-MP2510	211741		x	x	x	x	x	SR790			2	2		M0975602341
Ricoh	AF-MP2510	170494		x	x	x	x	x				2	2		M0975602743
Ricoh	AF-MP2510	158772		x	x	x	x	x	SR790			2	2		M0975700874
Ricoh	AF-MP2510	300155		x	x	x	x	x				2	2		M0975701253
Ricoh	AF-MP2510	130149		x	x	x	x	x				2	2		M0975800373
Ricoh	AF-MP2510	170444		x	x	x	x	x	SR790			2	2		M0975900220
Ricoh	AF-MP2510	23334		x	x	x	x	x	SR790			2	2	Dirty	M0976000560
Ricoh	AF-MP2510	25328		x	x	x	x	x	SR790			2	2		M0976000585
Ricoh	AF-MP2510	145470		x	x	x	x	x				2	2		M975303129
Ricoh	AF-MP2550	168362		x	x	x	x	x				2	2		M6585101656
Ricoh	AF-MP2550	114109		x	x	x	x	x				3	2	Permanently Soiled	M6585200043
Ricoh	AF-MP2550	256845		x	x	x	x	x				2	2		M6585200045
Ricoh	AF-MP2550	32228		x	x	x	x	x				2	2		M6585200110
Ricoh	AF-MP2550	107344		x	x	x	x	x	Hangin			2	2		M6585400227
Ricoh	AF-MP2550	38361		x	x	x	x	x				2	2		M6585600419
Ricoh	AF-MP2550	130992		x	x	x	x	x				2	2		M6585700626
Ricoh	AF-MP2550	2772		x	x	x	x	x				2	2		M6585700654
Ricoh	AF-MP2550	135671		x	x		x	x				2	2		M6585800196
Ricoh	AF-MP2550	178944		x	x		x	x				2	2		M6585801343
Ricoh	AF-MP2550	70494		x	x		x	x				2	2		M6585801407
Ricoh	AF-MP2550B	160922		x	x	x						2	2		M6485200342
Ricoh	AF-MP3000	598838	14514	x	x	x	x	x				2	2		L3765501178
Ricoh	AF-MP3010	159606		x	x		x	x	SR790			2	2		M1075600854
Ricoh	AF-MP3260C	143927	60313	x	x		x	x				2	2		K5961100228
Ricoh	AF-MP3350	291016		x	x	x	x	x				2	3	defective hdd error code SC876	M6385300351

**ACCESSORIES**

MAKE	MODEL	Total Meter	Color Meter	DF	Dup	FAX	PRT	SCAN	FIN	LCT	EC	IC	Comments	SN	
Ricoh	AF-MP3350	39906		x	x	x	x	x	SR-790			2	2		M6385700670
Ricoh	AF-MP3350B	263116		x	x	x						3	2	Plastic around screen slightly yellowed	M6285500069
Ricoh	AF-MP3350B	122553		x	x				SR790			2	2		M6285700453
Ricoh	AF-MP3500														M2766000720
Ricoh	AF-MP3500	373879		x	x	x	x	x	SR790			2	2		M2774901700
Ricoh	AF-MP3500	217407		x	x		x	x				2	2	missing hdd for universal send	M2775000831
Ricoh	AF-MP3500	379505		x	x	x	x	x				2	2		M2775600728
Ricoh	AF-MP3500	279472		x	x	x	x	x	SR790			2	2		M2775601057
Ricoh	AF-MP3500	367187		x	x		x	x	SR790			2	2		M2775601492
Ricoh	AF-MP3500	204694		x	x	x			SR790			2	2		M2775701360
Ricoh	AF-MP3500	286322		x	x	x	x	x	SR880			2	2		M2775900736
Ricoh	AF-MP3500	332793		x	x	x	x	x	SR880			2	2		M2775900763
Ricoh	AF-MP3500	734976		x	x	x	x	x	SR790			2	2		M2775901931
Ricoh	AF-MP3500	747397		x	x	x	x	x	SR790			2	2		M2776000544
Ricoh	AF-MP3500	782225			x		x	x	SR790			2	2		M2776000552
Ricoh	AF-MP3500	378274		x	x	x	x	x	SR890			2	2		M2776000569
Ricoh	AF-MP3500	756547		x	x	x	x	x	SR790			2	2		M2776000581
Ricoh	AF-MP3500	748794		x	x	x			SR790			2	2		M2776000585

**IMPACT TECHNOLOGY**  
608 7th St. NE Long Prairie, MN 56347  
866.848.4900

**RICOH**

Ricoh	AF-MP3500	707244		x	x		x	x	SR790		2	2		M2776000600
Ricoh	AF-MP3500	156823		x	x	x	x	x	SR880		2	2		M2776000824
Ricoh	AF-MP4000	273603		x	x	x	x	x	SR-3020		2	2		M5585401338
Ricoh	AF-MP4000	882543		x	x		x	x	SR-3030		3	2	Plastic around screen yellowed	M5585700838
Ricoh	AF-MP4420	17424		x	x	x					2	2		A4568800500
Ricoh	AF-MP4500	2243914		x	x		x	x	SR-790	x	3	2	LCD Screen non functioning	M2866000227
Ricoh	AF-MP4500	846016		x	x	x	x	x	SR790	x	2	2		M2874901122

**ACCESSORIES**

MAKE	MODEL	Total Meter	Color Meter	DF	Dup	FAX	PRT	SCAN	FIN	LCT	EC	IC	Comments	SN
Ricoh	AF-MP5000	404958		x	x	x	x	x	SR790		2	2		85000411
Ricoh	AF-MP5000	1038711		x	x		x	x			2	2		L8065500186
Ricoh	AF-MP5000	172218		x	x	x	x	x	SR3000		2	2		M5785600717
Ricoh	AF-MP5000	548471		x	x		x	x	SR3030		2	2		M5785700815
Ricoh	AF-MP5500	2392858		x	x						2	2		L7765300003
Ricoh	AF-MP5500	3168192		x	x				SR970		2	2		L7765500072
Ricoh	AF-MP5500	331610		x	x				SR970		2	2		L7775400146
Ricoh	AF-MP5500	253205		x	x	x	x	x	SR-970		2	2		L7785100373
Ricoh	AF-MP5500	1659023		x	x	x	x	x	SR970		2	2		L8065900346
Ricoh	AF-MP5510	29205		x		x					2	2		A3880290024
Ricoh	AF-MP6000	200206		x	x	x	x	x	SR970	x	2	2		M9285401004
Ricoh	AF-MP6000	964401			x		x	x	SR-790		2	2		M9285700471
Ricoh	AF-MP6500	1499221		x	x				S970		2	2		L7865400014
Ricoh	AF-MP6500	743183		x	x				SR-970		2	2		L7865500003
Ricoh	AF-MP6500	1381374		x	x				SR-970		2	2		L7865700038
Ricoh	AF-MP6500	1257785		x							2	2		L7865700067
Ricoh	af-MP6500	805856		x	x	x	x	x	SR970		2	2		L8175500136
Ricoh	AF-MP7500	4919637	97057	x	x		x	x	SR-5000		2	2		M8080300014
Ricoh	AF-MP9000			x	x		x	x	SR-5000		4	3	LCD Damaged/Arrived with back of machine in pieces/Both controllers were off/Hinges broken/Cant test or get to meter or options	L5570200068
Ricoh	AF-MP9000	1763737		x	x		x	x	SR5000		2	3	SC860 HDD error	L5580200054
Ricoh	AF-MPC2000	121455	13081	x	x	x	x	x	SR3000		2	2		M0575900336
Ricoh	AF-MPC2000	68654	36713	x	x		x	x	SR-790		2	2		M5084900797
Ricoh	AF-MPC2500	1054338	178692	x	x	x	x	x			2	2	SC535 fuser error cannot test	L3665300052
Ricoh	AF-MPC2500	463372	394613	x	x	x	x	x			2	2		L3665500041
Ricoh	AF-MPC2500	311761	57683	x	x	x	x	x	SR3030		2	2		L3665600523

**ACCESSORIES**

MAKE	MODEL	Total Meter	Color Meter	DF	Dup	FAX	PRT	SCAN	FIN	LCT	EC	IC	Comments	SN
Ricoh	AF-MPC2500	158372	22846	x	x		x	x			2	2		L3665800276
Ricoh	AF-MPC2500	240000	80912	x	x	x	x	x	SR790		2	2	Missing 4 toners	L3665800283
Ricoh	AF-MPC2500	209000	89728	x	x		x	x	SR790		2	2		L3665900765
Ricoh	AF-MPC2500	114492	44432	x	x	x	x	x			3	2	Touch Panel Does not work	L3674900488
Ricoh	AF-MPC2500	395441	121434	x	x	x	x	x			2	2		L3675000266
Ricoh	AF-MPC2500	194539	49567	x	x		x	x	SR3030		2	2		L3675000628
Ricoh	AF-MPC2500	328377	225907		x	x	x	x	SR3000		2	2		L3675202149
Ricoh	AF-MPC2500	198137	75383	x	x	x	x	x	SR790		2	2		L3675202237
Ricoh	AF-MPC2500	176181	65132	x	x	x	x	x	SR3010		2	2	Missing 4 Toners	L3675300035
Ricoh	AF-MPC2500	317046	3232	x	x	x	x	x			2	2		L3675700391
Ricoh	AF-MPC2500	499944	61074	x	x	x	x	x			2	2		L3675700542
Ricoh	AF-MPC2500	74168	50433	x	x	x	x	x			2	2		L3675800677
Ricoh	AF-MPC2500	288686	57920	x	x	x	x	x			2	2		L3675900474
Ricoh	AF-MPC2500			x	x		x	x			3	2	Touch panel does not work	L3675900980
Ricoh	AF-MPC2500	182712	66965	x	x	x	x	x			2	2		L3676000010
Ricoh	AF-MPC2500	111144	39483	x	x	x	x	x	Hanging		2	2		L3676000688
Ricoh	AF-MPC3000	243034	9413	x	x	x	x	x			2	2		L3765500195
Ricoh	AF-MPC3000	305082	128527	x	x	x	x	x	SR-3000		2	2		L3765501051
Ricoh	AF-MPC3000	246169	59604	x	x	x	x	x	SR790		2	2		L3765900894
Ricoh	AF-MPC3000	191544	105322	x	x	x	x	x	SR790		2	2		L3775200189
Ricoh	AF-MPC3000	365061	102036	x	x	x	x	x	DR-790		2	2		L3775700116

**IMPACT TECHNOLOGY**  
608 7th St. NE Long Prairie, MN 56347  
866.848.4900

**RICOH**

Ricoh	AF-MPC3000	88848	13566	x	x				x	SR-790		2	2	Global Scan	L3775800285
Ricoh	AF-MPC3000	145900	33012	x	x	x	x	x	x	SR790		2	2		L3785100020
Ricoh	AF-MPC3000	258771	76065	x	x	x	x	x	x	SR790		2	2		L3785100178
Ricoh	AF-MPC3000	126089	26131	x	x	x	x	x	x	SR790		2	2		L3785400025

**ACCESSORIES**

MAKE	MODEL	Total Meter	Color Meter	DF	Dup	FAX	PRT	SCAN	FIN	LCT	EC	IC	Comments	SN
Ricoh	AF-MPC3000	38755	15292	x	x	x	x	x	SR790		2	2		L3785500239
Ricoh	AF-MPC3300	274709	44983	x	x	x	x	x	SR-790		2	2		V1594900825
Ricoh	AF-MPC3300	252636	21861	x	x	x	x	x			2	2		V1595500175
Ricoh	AF-MPC3500	746071	504110	x	x	x	x	x			2	2	Transfer belt handle broken	L8966700163
Ricoh	AF-MPC3500	893713	47994	x	x		x	x	SR-790		2	2		L8966820329
Ricoh	AF-MPC3500	838371	46931	x	x	x	x	x	SR-790		2	2		L8966920473
Ricoh	AF-MPC3500	212561	36393	x	x		x	x	SR3030		2	2		L8967020573
Ricoh	AF-MPC3500	744755	252762	x	x		x	x	SR790		2	2		L8976120337
Ricoh	AF-MPC3500	475050	343044	x	x	x	x	x	SR790		2	2	Missing 4 toners	L8976120339
Ricoh	AF-MPC3500	190107	100612	x	x	x	x	x	SR3030		2	2		L8976121155
Ricoh	AF-MPC3500	465600	97893	x			x	x	SR-3030		3	2	Cover above bypass broken	L8976121228
Ricoh	AF-MPC3500	572139	167392	x	x	x	x	x	SR-790		2	2	Missing Toners	L8976321349
Ricoh	AF-MPC3500	705572	219112	x	x	x	x	x			2	2		L8976321539
Ricoh	AF-MPC3500	323128	169626	x	x	x	x	x	SR3030		2	2		L8976321848
Ricoh	AF-MPC3500	351911	171951	x	x	x	x	x	SR3020		2	2		L8976420944
Ricoh	AF-MPC3500	416825	143162	x	x	x	x	x	SR3020		2	3	SC120 Scanner Home Position Error 1	L8976421744
Ricoh	AF-MPC3500	242124	176960	x	x	x	x	x	SR3030		2	2	Missing 3 toners	L8976620076
Ricoh	AF-MPC3500	354824	64568	x	x	x	x	x	SR790		2	2	Missing 4 toners	L8976720443
Ricoh	AF-MPC3500	642289	273781	x	x	x	x	x	SR3030		2	2	missing all 4 toners	L8977120150
Ricoh	AF-MPC3500	404642	189254	x	x		x	x	SR-3030F		2	2	MIssing toners	L8977120532
Ricoh	AF-MPC3500	406036	141750	x	x		x	x			2	2		L8977220899
Ricoh	AF-MPC3500	200618	121491	x	x	x	x	x	SR3030		2	2		L8986120541
Ricoh	AF-MPC3500	208873	125670	x	x	x	x	x	SR3030		2	2		L8986320273
Ricoh	AF-MPC3500	299077	271424	x	x	x	x	x			2	2		L8986421156
Ricoh	AF-MPC3500	346979	170875	x	x	x	x	x	SR3030		2	2		L8986521664

**ACCESSORIES**

MAKE	MODEL	Total Meter	Color Meter	DF	Dup	FAX	PRT	SCAN	FIN	LCT	EC	IC	Comments	SN
Ricoh	AF-MPC3500	186392	52112	x	x	x	x	x	SR3030		2	2		L8986620492
Ricoh	AF-MPC3500	608183	384527	x	x	x	x	x	SR3030		2	2		L8986721552
Ricoh	AF-MPC4000	310591	8951	x	x	x	x	x			2	2		V1286000943
Ricoh	AF-MPC4500	320605	124407	x	x		x	x	SR790		2	2		L9060700023
Ricoh	AF-MPC4500	782564	65765	x	x		x	x	SR3020		2	2		L9066600206
Ricoh	AF-MPC4500	656263	27146	x	x		x	x	SR3030		2	2		L9066700050
Ricoh	AF-MPC4500	410064	52487	x	x		x	x	SR3030		2	2		L9067020251
Ricoh	AF-MPC4500	428917	135628	x	x	x	x	x	SR790		2	2		L9067020375
Ricoh	AF-MPC4500	407022	249817	x	x	x	x	x	SR3030		2	2		L9067021211
Ricoh	AF-MPC4500	653583	272763	x	x	x	x	x	SR3030		2	2		L9067120567
Ricoh	AF-MPC4500	435959	225574	x	x	x	x	x	SR3020		2	3	SC553 Pressure Roller Overheat	L9067120658
Ricoh	AF-MPC4500	571240	84988	x	x	x	x	x	SR-3030		2	2		L9076121555
Ricoh	AF-MPC4500	784806	75288	x	x	x	x	x	SR-3030		2	2	Missing toners	L9076320695
Ricoh	AF-MPC4500	240660	46063	x	x	x	x	x	SR790		2	2		L9076420477
Ricoh	AF-MPC4500	356220	110174	x	x	x	x	x	SR3030		2	2		L9076620481
Ricoh	AF-MPC4500	855571	142632	x	x		x	x	SR3020		2	2		L9086120073
Ricoh	AF-MPC4500	1202568	321675	x	x	x	x	x	SR3030		2	2		L9086120277
Ricoh	AF-MPC4500	626357	200376	x	x	x	x	x	SR3030		2	2		L9086120728
Ricoh	AF-MPC4500	487029	156777	x	x	x	x	x			2	2		L9086320554
Ricoh	AF-MPC4500	384936	50737	x	x	x	x	x	SR790		2	2		L9086521526
Ricoh	AF-MPC4500	217155	73971	x	x		x	x	SR3030		3	2	Broken wheel	L9086720594
Ricoh	AF-MPC4500	288009	92870	x	x	x	x	x	SR-790		2	2		L9086721185
Ricoh	AF-MPC5000	344259	304249	x	x		x	x			2	2		V1305000028
Ricoh	AF-MPC5000	449304	345850	x	x	x	x	x	SR-3030		2	2		V1385700270
Ricoh	AF-MPC5000	374097	115743	x	x	x	x	x	SR-790		2	2		V1385700285

**ACCESSORIES**

MAKE	MODEL	Total Meter	Color Meter	DF	Dup	FAX	PRT	SCAN	FIN	LCT	EC	IC	Comments	SN
------	-------	-------------	-------------	----	-----	-----	-----	------	-----	-----	----	----	----------	----

**IMPACT TECHNOLOGY**  
608 7th St. NE Long Prairie, MN 56347  
866.848.4900

**RICOH**

Ricoh	AF-MPC5000	243214	127717	x	x		x	x	SR-3020		2	2		V1385700636
Ricoh	AF-MPC6000	1447188	474470	x	x		x	x	SR5000		2	2		M7971200153
Ricoh	AF-MPC6000	503834	369523	x	x		x	x	SR-970		2	2		M7971200165
Ricoh	AF-MPC6000	1092926	377668	x	x	x	x	x	SR-4010		2	3	SC540 Fuser motor error	M7980100156
Ricoh	AF-MPC6000	1892792	410449	x	x		x	x	SR-4020		2	2		M7980400080
Ricoh	AF-MPC6000	536092	453753	x	x		x	x	SR4020		2	2		M7980400131
Ricoh	AF-MPC6000	1178807	580069	x	x	x	x	x	SR4010		2	2		M7980400439
Ricoh	AF-MPC6000	1191978		x	x		x	x	SR-5000		2	2		M7980700252
Ricoh	AF-MPC6000	1096267	138082	x	x		x	x	SR4010		2	2		M7980700354
Ricoh	AF-MPC6000	397111	299809	x	x		x	x	SR-5000		2	2		M7980800333
Ricoh	AF-MPC6000	339612	200036	x	x		x	x	SR-5000		2	2		M7980900042
Ricoh	AF-MPC6000	326034	155077	x	x		x	x	SR-5000		2	2		M7980900110
Ricoh	AF-MPC6000	531542	22672	x	x		x	x	SR5000		2	2		M7980900496
Ricoh	AF-MPC6000	171724	134273	x	x		x	x	SR-5000		2	2		M7981000075
Ricoh	AF-MPC6000	757786	372602	x	x		x	x	SR4010		2	2		M7981200683
Ricoh	AF-MPC6000	302462	130128	x	x		x	x	SR4020		2	2		M7990500264
Ricoh	AF-MPC7500	830851	236881	x	x		x	x	SR-5000		2	2		M8071200096
Ricoh	AF-PRO1106EX	1922667		x	x		x	x	SR-4020	x	2	2		V0981000131
Ricoh	AF-SC4100N	48053					x				2	2		S2086300134
Ricoh	AF-SC4100N	77700					x				2	2		S2086400316
Ricoh	AF-SC4100N	133273					x				2	2		S2086400587
Ricoh	AF-SC4100N	155577					x				2	2		S2086400703
Ricoh	AF-SC4100N	14326					x				2	2		S2086400709
Ricoh	AF-SC4100N	172124					x				2	2		S2086500552
Ricoh	AF-SP3200SF	72127		x		x	x				2	2		S2579400043

**ACCESSORIES**

MAKE	MODEL	Total Meter	Color Meter	DF	Dup	FAX	PRT	SCAN	FIN	LCT	EC	IC	Comments	SN
Ricoh	AF-SP4000n						x				5	3	Machine freezes while printing	S2076200166
Ricoh	AF-SP4100N	21363									2	2		S2086400701
Ricoh	AF-SP4100N	151686									2	2		S2086400702
Ricoh	AF-SP4100N	65434					x				2	2		S2086400704
Ricoh	AF-SP4100N	8084					x				2	2		S2086400705
Ricoh	AF-SP4100N	29654					x				2	2		S2086400707
Ricoh	AF-SP4100N	49885					x				2	2		S2086400708
Ricoh	AF-SP4100N	133063					x				2	2		S2086400710
Ricoh	AF-SP4100N	86652					x				2	2		S2086400711
Ricoh	AF-SP4100N	38515									2	2		S2086400712
Ricoh	AF-SP4100N	55391									2	2		S2086400713
Ricoh	AF-SP4100N	33651									2	2		S2086400714
Ricoh	AF-SP4100N	54044					x				2	2		S2086400715
Ricoh	AF-SP4100N	366740					x				2	2		S2086400716
Ricoh	AF-SP4100N	45602					x				2	2		S2086500191
Ricoh	AF-SP410DN	60959	18491				x				2	2		Q7078600686
Ricoh	AF-SP4110N	16					x				2	2		S0889000084B
Ricoh	AF-SP4110N	40					x				2	2		S0889000102B
Ricoh	AF-SP4110N	17			x		x				2	2		S088900041B
Ricoh	AF-SP4110N	9443					x				2	2		S0889300234
Ricoh	AF-SP420DN	135142	49384		x		x				2	2		S3889203151
Ricoh	AF-SP4210N	14385					x				2	2		S5298501089
Ricoh	AF-SP811DN	336066	286403				x				2	2		Q8067000023
Ricoh	AF-SPC400DN	35622	18099				x				2	2		Q6888600103
Ricoh	AF-SPC410DN	108111	56927				x				2	2		Q7078700460

**ACCESSORIES**

MAKE	MODEL	Total Meter	Color Meter	DF	Dup	FAX	PRT	SCAN	FIN	LCT	EC	IC	Comments	SN
Ricoh	AF-SPC410DN	28236	26988				x				2	2		Q7079100622
Ricoh	AF-SPC411DN	60444	35840	x			x				2	2		Q7188500086
Ricoh	AF-SPC811DN	1018981	435448				x				2	2		Q8067000327
Ricoh	AF-SPC811DN						x				2	3		Q8067000479
Ricoh	AF-SPC811DN	58831	51084				x				2	2		Q8067000616
Ricoh	AF-SPC811DN	863947	795174		x		x		3000F		2	2		Q8076340273
Ricoh	AF-SPC811DN	185998	63952				x		SR3000		2	2		Q8086140363
Ricoh	AF-SPC811DN	122816	114908				x				2	2		Q8086540188
Ricoh	AP-400N	204569		x	x						2	2		Q0146800324
Ricoh	AP-400N	214245			x						2	2		Q0247200461

**IMPACT TECHNOLOGY**  
608 7th St. NE Long Prairie, MN 56347  
866.848.4900

**RICOH**

Ricoh	FT3213	106722									2	2	FT	A3615011994
Ricoh	GX3000										2	3	No Ink	R0768200051
Ricoh	IS-300E										2	2		Q2370100091
Ricoh	IS-450DE										2	2	Scanning unit, cannot test	P1340300010
Ricoh	IS-450DE										2	2		P1341200029
Ricoh	JP-1235	143368									2	2		2630750087
Ricoh	MP-2550	289732		x	x	x	x	x			2	2		M6585102221
Ricoh	MP-3010SPF	193634		x	x	x	x	x	SR-790		3	2	Broken Wheel	M1075600755
Ricoh	MP-4000	602632		x	x	x	x	x			2	2		M5585400697
Ricoh	MP-4000													M5585500431
Ricoh	MPC-2500SPF	77356	28061	x	x	x	x	x			2	2		L3675501535
Ricoh	MPC-4500	204197	27651	x	x	x	x	x	SR-790		2	2		L9076620659
Ricoh	Priport DX4545	140368		x	x						2	3	right side cab. door hinge pin broke	N7190500011
Ricoh	SPC-811DN	65403	42745	x				x			2	2		Q8086740113
Savin	2055DP	1628557		x	x			x	SR740		2	2		H4705400209

**ACCESSORIES**

MAKE	MODEL	Total Meter	Color Meter	DF	Dup	FAX	PRT	SCAN	FIN	LCT	EC	IC	Comments	SN
Savin	2055DP	1816494		x	x		x		SR740		2	2		H4715200667
Savin	2055DP	1625209		x	x		x		SR740		2	2		H4715200682
Savin	2055DP	3057134		x	x		x		SR790		4	2	back panel busted- ADF broken- left side panel cracked	H4715200754
Savin	2055DP	2019796		x	x		x		SR740		2	2		H4715200816
Savin	2055DP	1862894		x	x		x		SR740		2	2		H4715500803
Savin	2070DP	1401234		x	x				SR830	x	2	2		H4805300069
Savin	2513	187472			x		x				2	2	Flat Top	H9038600151
Savin	2513	655384		x	x	x	x				2	2		H9229101359
Savin	2513	191136		x	x	x	x				2	2		H9238600091
Savin	2513	194793		x	x	x	x				2	2		H9238600331
Savin	2522	247956		x	x	x	x	x			2	2		J0131303092
Savin	2535	965397		x	x						3	2	Discolored	H7016500028
Savin	2535	617621		x	x						4	2	Missing Wheel	H7016601159
Savin	2535	589192		x	x		x				2	2		H7216400469
Savin	2545	615879		x	x		x				2	2		H7316500002
Savin	3350DNP	3395286									2	2		C377112007
Savin	3515	9912		x		x	x	x			4	3	Machine toner spilled will not pass copy	K2068801039
Savin	3515	60365		x		x					2	2		K2269200305
Savin	3535F	737967	364484	x	x	x	x	x	SR3020		2	2		L8977020272
Savin	3560	26006				x					2	2		A4568900416
Savin	3760	66041				x					2	2		A4569200245
Savin	4018	82786		x	x						2	3	SC620 Communication Error Between BICU	J9146700903
Savin	4022	778999		x	x	x	x				2	2	Missing options exterior buttons	J8341302154
Savin	4022Sp	302498		x	x	x	x	x			2	2		J8341302288
Savin	4045	529518		x	x				SR-790	x	5	3	Power cord cut/Need to rewire entirely/Cant test or get to options	K2945200230

**ACCESSORIES**

MAKE	MODEL	Total Meter	Color Meter	DF	Dup	FAX	PRT	SCAN	FIN	LCT	EC	IC	Comments	SN
Savin	4045e	926080		x	x	x	x				2	2	No HDD/Image is black	J8046100409
Savin	4045e	1066104		x	x				SR790		2	2		K2955301221
Savin	4051	853214		x	x		x	x	SR-880		2	2		K4465000017
Savin	4060	1272761		x	x		x	x	SR-850		2	2		K6855700478
Savin	8016	136679		x		x	x	x			2	2		K8156940139
Savin	8016	82560		x	x						3	2	Discolored	K8166840519
Savin	8025	470614		x	x						4	5	Missing All control boards will not boot	K8565100308
Savin	8025e	87122		x	x	x	x	x			2	2		M0966001174
Savin	8025E	341049		x	x	x	x	x			2	2		M0975002235
Savin	8025E	105569		x	x	x	x	x	SR790		2	2	Removed fax and machine will pass copy/ machine heavily damaged	M0975701888

**IMPACT TECHNOLOGY**  
608 7th St. NE Long Prairie, MN 56347  
866.848.4900

**RICOH**

Savin	8030	167374		x	x		x		SR790		2	2		K8665101145
Savin	8030	67993		x	x		x	x			2	2		K8665200635
Savin	8030	124259		x	x	x	x	x			3	2	drawer 1 broken, scratches on machine, missing the bypass tray	K8665200636
Savin	8030	74042		x	x	x	x	x			2	2		K8665200638
Savin	8030	613029		x	x	x	x	x			2	2		K8665200639
Savin	8030	156303		x	x		x	x			2	2		K8665300245
Savin	8030	88639		x	x		x	x			3	2	Dirtied, broken wheel,	K8665600516
Savin	8030e	219117		x	x		x	x	SR790		2	2		M1076000554
Savin	8035	628274		x	x		x	x	SR-790		2	2		9365602543
Savin	8035e	282224		x	x	x	x	x			2	2		M2775601110
Savin	8035SP	579065		x	x	x	x	x	SR790		2	2		K9365701804
Savin	8045	519744		x	x		x		SR-880	x	3	2	Crack on back of machine	K9455800285
Savin	8045	123619		x		x	x		SR-790		2	2	scratches on front of machine, Finisher damaged	K9465700245
Savin	8045	336934		x	x	x	x	x	SR-790		2	2		K9465900962
Savin	8045e	279946		x		x	x		SR-790		3	2	Cover under the display is cracked/ Finisher damaged	J6470600370

**ACCESSORIES**

MAKE	MODEL	Total Meter	Color Meter	DF	Dup	FAX	PRT	SCAN	FIN	LCT	EC	IC	Comments	SN
Savin	8045E	378200		x	x	x	x	x			2	2		M2875100829
Savin	8060	325657		x	x		x	x	SR970		2	2		M9285300420
Savin	8075	1244915		x	x				SR841		2	2		L7965800099
Savin	8075	2395343		x	x		x	x	SR970		2	2		L8275400263
Savin	8090	4243539		x	x		x	x	SR5000		2	2		L5560400059
Savin	9025	133779		x	x	x	x	x			2	2		M6584900879
Savin	9025	190995		x	x	x	x	x			2	2	Needs new toner	M6584900946
Savin	9025	125954		x	x		x	x	SR790		2	2		M6585500696
Savin	9027DL	428640		x	x				ST10	x	2	2		1A55020043
Savin	9033	134820		x	x	x	x	x	SR3050		2	2		M6385500744
Savin	920SPF	4334		x	x	x	x	x			2	2		W3018505484
Savin	9918	211441		x	x						2	2		H1700500518
Savin	9922	579997		x	x						2	2		H2400600225
Savin	AC104			x		x					3	5	ADF broken/Machine will not boot	K2549400717
Savin	AC205			x		x					2	2		Q9169500578
Savin	C-9025SPF	189973	25041	x	x	x	x	x			3	2	Back right corner cracked	V2485900384
Savin	C2020	53680	13403	x	x	x	x	x			2	2		M5085600519
Savin	C2410	53513	15970	x	x	x	x	x			2	2		K7156600128
Savin	C2525	96239	23050	x	x	x	x	x			3	2	Crack on front door	L3665500585
Savin	C2525			x	x	x	x	x			3	2	Touch screen does not work	L3665901806
Savin	C2525	283794	62558	x	x	x	x	x	Hanging Finisher		2	2		L3675500614
Savin	C2525	551469	351406	x	x	x	x	x	SR790		2	2		L3675900973
Savin	C2525	132707	54340	x	x		x	x	Hanging		2	2		L3685100941
Savin	C2525			x	x	x	x	x			2	3	LCD touch screen non functioning/Cant get to meter or test	L3685200120
Savin	C2820	395617	82329	x	x	x	x	x	SR950		2	2		K4341000732

**ACCESSORIES**

MAKE	MODEL	Total Meter	Color Meter	DF	Dup	FAX	PRT	SCAN	FIN	LCT	EC	IC	Comments	SN
Savin	C2824	107234	21635	x	x	x	x	x	SR960		2	3	SC440-02 Main Motor Lock/Drum Motor Loc	K5250600042
Savin	C3030	178784	53877	x	x		x	x	SR790		2	2		L3765500352
Savin	C3210	392115	219296	x	x	x	x	x			2	3	SC571 Error	J2630901312
Savin	C3210	844271	118244	x	x	x	x	x			2	2		J2636201128
Savin	C3210	280426	35892	x	x	x	x	x	SR-790		2	2		J2637101272
Savin	C3224			x	x	x	x	x			3	4	Yellowed/Missing Fuser unit	K0250300201
Savin	C3528	574788	175309	x	x	x	x	x	SR960		2	2		K5060400536
Savin	C3535	88725	30625	x	x		x	x			2	2		L8967220200
Savin	C3535	593485	193955	x	x	x	x	x	SR790		2	2	Missing 4 toners	L8976321717

**IMPACT TECHNOLOGY**  
608 7th St. NE Long Prairie, MN 56347  
866.848.4900

**RICOH**

Savin	C3535	204025	80218	x	x		x	x	SR790		2	2		L8976520807
Savin	C4535	379424	35350	x	x	x	x	x			2	2		K5160200001
Savin	C4535	353287	140586	x	x	x	x	x	SR-960		2	2		K5160401015
Savin	C4535	874584	276554	x	x	x	x	x	SR690		2	2		K5160600358
Savin	C4540	309777	185315	x	x	x	x	x			2	2		L9067220768
Savin	C4540	437754	150200	x	x	x	x	x			2	2		L9067220790
Savin	C4540	625512	90900	x	x		x	x			2	2		L9076320423
Savin	C4540SP	360115	125268	x	x	x	x	x	SR-3020		2	2		L9086420851
Savin	C6045	268161	57337	x	x		x	x	SR-970	x	2	2	Makes loud noise when in operation	K590700184
Savin	C6045	1403847	984733	x	x		x	x	SR980		2	2		K5951100271
Savin	C6045	1348876	853083		x		x	x	SR-970		2	2		K5970300177
Savin	C6055	506795	222446	x	x	x	x	x	SR970		2	2		M7980300258
Savin	C9025	334547	272416	x	x		x	x			2	2		V24859516
Savin	CLP240D	36840	26143				x				2	2		Q8077040222
Savin	CLP31DN	47609	45265				x				2	2	2 trays	Q7179400017
Savin	SDC-413	693628	377851	x	x		x	x	ST33		2	2		H6311200294

**ACCESSORIES**

MAKE	MODEL	Total Meter	Color Meter	DF	Dup	FAX	PRT	SCAN	FIN	LCT	EC	IC	Comments	SN
Savin	SDC-555	1152769	731406	x	x		x	x	SR-980	x	2	2		K6050500137
Savin	SDC555	658042	595231	x	x		x	x	SR970		2	2		K6051200003